

SPRINKLER SYSTEM INSPECTION CERTIFICATE

This is to certify the system referred to below was inspected in accordance with the national fire code and the requirements of the authority having jurisdiction and was found to be in proper working order when the inspection was completed.

THIS CERTIFIES that the Partial Dry Fire Sprinkler equipment inspected on January 15,2020

Located at ____ The Darlington Arms. 317- 14th Avenue SW Calgary AB T2R 0M4
Was checked, inspected and serviced by a trained technician.

Next Inspection: January 2020

CAN/ULC S536-04 / NFPA10-10 / CSA 22.2 / NFPA25-11 NFPA17A-09

Authorized Signature

THIS CERTIFICATE SHOULD BE AFFIXED ADJACENT TO THE SYSTEM